



Bovis

Lend Lease

Global Alliance

Environment, Health & Safety Alert

Refrigeration Near Miss

From: Martin Rackley Global Alliance HSSE Manager

Ref. No B/02

Date: 3.02.06



A recent routine maintenance audit at Craigpark Connect discovered missing fan guards to refrigeration evaporator fans, which had been removed by engineers on previous visits (top right). The fans continued to operate even after the main cabinet switch was turned off. XXXX was contacted to send an engineer to site the same day. When the engineer arrived the situation allegedly went from bad to worse. It is reported that the engineer

- Didn't sign the site register
- Didn't produce a PIA passport
- Didn't complete a clearance cert and produce his method statement
- Didn't isolate the cabinet and worked on it live
- Didn't barricade and protect the area from customers and staff and exposed them to live electrical wiring (see top left)

The engineer has been prohibited from working on BP sites in future. XXXX is completing an urgent review of its procedures to ensure only qualified staff with PIA passports and who demonstrate the correct behaviours are sent to work on our sites. We are also investigating how the removal of the fan covers and the faulty isolation switch were not highlighted by previous crews.

ALWAYS REPORT FAULTY EQUIPMENT / MISSING PARTS. OTHERWISE YOU ARE LEAVING POTENTIAL HAZARDS FOR OTHERS. TAKING SHORTS CUTS WILL BE DISCOVERED. THINK OF THE CONSEQUENCES FOR YOU AND YOUR COMPANY!

SITE MANAGERS / SUPERVISORS TO BRIEF STAFF AND DISPLAY ON SITE / COMPANY NOTICE BOARD.

SIGN OFF RECORD

Print Name	Signature	Print Name	Signature	Print Name	Signature